



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Outgoing
C0070038
4405
K

October 2, 2013

Mr. Dennis Ware
Plateau Mining Company
P.O. Box 30
Helper, Utah 84526-0030

Subject: Authorization to Proceed, Plan To Repair Storm Damaged Channels, Task ID #4405, Plateau Mining Company, Willow Creek Mine, C/007/0038

Dear Mr. Ware:

The Division is in agreement with the work plan to repair the storm damaged channels (received on September 27, 2013). This authorization to proceed includes the following specific measures to be employed to limit damage to the reclaimed area as discussed in our telephone conversation today:

- The integrity of the four feet of cover material will be maintained in re-disturbed areas.
- The limits of the truck turn-around area will be identified with markers.
- Compaction of the truck turnaround will be alleviated by ripping and seeding after use.

As agreed, you will provide the Division with as-built information on the quantity, source and physical characteristics of the imported fill. The submitted plan of work does not amend the existing reclamation plan and does not necessitate an update to the Technical Analysis.

If you have any questions, please feel free to call me at (801) 538-5325.

Sincerely,

Steve Christensen
Permit Supervisor

SKC/PWB/ss
O:\007038.WIL\WG4405\WG4405App.doc

